



REPLY TO
ATTENTION OF

DEPARTMENT OF THE ARMY
UNITED STATES ARMY AVIATION AND MISSILE COMMAND
REDSTONE ARSENAL, ALABAMA 35898-5000

24 JAN 2000

AMSAM-RD-AE-I-P-A

MEMORANDUM FOR SEE DISTRIBUTION

SUBJECT: Interim Statement of Airworthiness Qualification
(ISAQ) for AH-64A Helicopter, Revision 6

1. References:

a. Interim Statement of Airworthiness Qualification (ISAQ),
AH-64A Helicopter, 30 Jul 98.

b. Interim Statement of Airworthiness Qualification (ISAQ),
AH-64A Helicopter, revision 5, 26 Aug 99.

2. The purpose of this revision is to allow an extension, until
28 Feb 2001, to the operation of the following three components:

Item	Part Number
Lead Lag Damper	7-311411110
Trunnion Damper	7-311411187
Pitch Housing	7-311411215

Revision 6 will supersede revision 5 for these three components
only and nothing else.

3. The following changes fatigue life hours for the "A" model
on three Apache parts which are common to the "D" model Apaches.
The part numbers listed cover the basic and all subsequent dash
numbers unless parts are specifically identified by dash number.

4. The fatigue life hours become effective upon signature of
this revision. Units not having sufficient assets for
implementation of these new fatigue lives listed in revision 5,
are granted a grace period to procure and replace affected
components. This grace period is only for "A" model Apache
implementation and will not exceed the fatigue life of the
component listed below or 28 February 2001, whichever comes
first.

AMSAM-RD-AE-I-P-A

SUBJECT: Interim Statement of Airworthiness Qualification (ISAQ)
for AH-64A Helicopter, Revision 6

5. During this 12 month grace period, components removed from "D" model Apache aircraft, but not exceeding the "A" model fatigue lives listed in reference 1.b, **shall not** be installed on an "A" Model Apache aircraft regardless of usable service hours remaining. If a component is being installed from supply, a records check is to be performed to insure the component was never installed on a "D" model. Once the component is removed from an aircraft, the grace period shall no longer be applicable and the new fatigue lives listed in reference 1.b will then apply.

Component	Part Number	Flight Hours Life Until 29 Feb 2000	Life From 01 Mar 2000 to 28 Feb 2001
Lead lag damper	7-311411110	3710	3228
Trunnion, damper	7-311411187	2739	2223
Pitch housing	7-311411215	1918	1553

6. This memorandum shall be attached to, and become a permanent part of the referenced ISAQ. This revision is effective as of 01 March 2000 and will remain in effect until 28 February 2001, unless rescinded or superseded.

7. The point of contact for this action is Mr. Lee Bumbicka, AMSAM-RD-AE-I-P-A, DSN 897-4925 or Commercial (256) 313-4925, E-mail: lee.bumbicka@redstone.army.mil


BARRY J. BASKETT
Director of Aviation Engineering

DISTRIBUTION:

Commander:

2/6th Cavalry, ATTN: AETV-AVA-V-A, CMR 416, APO AE 09140

6/6th Cavalry, ATTN: AETV-AVA-CS, CDR 416, APO AE 09140

11th Aviation Brigade, ATTN: AETS-AVA, APO AE 09140

7th/159th, ATTN: AETS-SC-AV-A, APO AE 09140

DISTRIBUTION: (CONT)

4th Combat Aviation Brigade, 1st Armored Division,
ATTN: AETV-TFJ, APO AE 09165